



Katherine Drolett <drolettlaw@gmail.com>

Re: Sink hole Soulshine

1 message

Chris Fisher <ChrisF@jmwilliamscontractors.com>

Mon, Sep 10, 2018 at 9:45 AM

To: Katherine Drolett <drolettlaw@gmail.com>, John Norton <johnn@jmwilliamscontractors.com>, Scott Craig <scottc@jmwilliamscontractors.com>

Katherine,

To add to Scott's information, as he stated, the depth of the hole is hard to determine as the slabs are in the way of an accurate measurement of the depth. The slabs have dropped at the west end about 6" since discovered in July. The south and north walls that can be seen have not deteriorated much. The west wall however has had the most change. As Scott mentioned we placed a control board to measure from and it shows approximately a 5-7/8" Change in the last 2 weeks with a width change of an overall 36". The possible cause is vibration from the street and daily activity in the building. Also that the city placed water in the hole for testing purposes has made the materials relatively moist.

Thank you.

Chris Fisher

229-740-0869

chrisf@jmwilliamscontractors.com

From: Scott Craig**Sent:** Monday, September 10, 2018 8:52:14 AM**To:** Katherine Drolett; Chris Fisher; John Norton**Subject:** Re: Sink hole Soulshine

Katherine

The depth will be hard to determine since the slab is still in the way, however the diameter has changed significantly especially at the Willy's side.

Chris has a 2x4 placed in the hole vertically to give us a reference point and I'm sure he'll send something over to you shortly.

Thank you!

Scott

Scott Craig

Superintendent

From: Katherine Drolett <drolettlaw@gmail.com>**Sent:** Monday, September 10, 2018 8:40 AM

To: Chris Fisher; Scott Craig; John Norton
Subject: Sink hole Soulshine

Chris and Scott -

Can you tell me how much the sink hole has grown width and possibly depth since first discovered and the average rate it is growing - if you know?

Thanks guys!!

Katherine Drolett
404-610-0800

Soulshine Sinkhole Pictures

1 message

John Norton <johnn@jmwilliamscontractors.com>
To: "Dave@icanfixamerica.com" <Dave@icanfixamerica.com>
Cc: Katherine Drolett <drolettlaw@gmail.com>

Fri, Sep 7, 2018 at 9:05 AM

David,

Please see attached sinkhole pictures. It difficult to tell via the pictures but the hole is definitely growing. Chris Fisher, our site super, has been monitoring the erosion on a daily basis. It's not eroding at great rate, but it is steadily growing which is a concern. Pictures 4467, 8765, & 8688 were taken when we discover the hole (July 1st +/-). Pictures 7880 & 9989 were taken earlier this week.

Sincerely,

John M. Norton

Operations Manager



mobile | 770-776-7480

office | 678-242-3015

JMWilliamsContractors.com

ATLANTA • AUBURN • TAMPA

Home Office:

[400 Franklin Gateway](#)

[Suite 200](#)

[Marietta, GA 30067](#)

5 attachments



IMG_20180711_215114467_LL.jpg
5559K



IMG_20180711_215118765_LL.jpg
5292K



IMG_20180827_103848688_LL.jpg
1772K



IMG_20180827_104217880_LL.jpg
1409K

IMG_20180906_104739989.jpg
1372K

