

Work Order 2200680

Printed: 10/04/2018 8:35 am

Work Order Activity:

Activity: WCTV04 CCTV LINE

Asset Information:

Unit ID: From - to -

Descript:

Comp Type: FEQ - Fleet Equipment

Address:

City: ,

X Coord: 1.00

Y Coordinate: 1.00

Z Coordinate: 1.00

Map Nbr:

Area:

Sub Area:

Qualifier:

Work Order Information:

Initiated: 07/23/2018

Source: RI - Ransomware Incident

Authorization: W102 - KIMBRY PEEK

Init By: ADRIAN MORRIS

Maint Type: INSP - INSP

Assigned: ARKIETHON L HARDEN

Scheduled: 07/23/2018

Problem: CVN01 - CAVEIN-ST/SW SINK

Responsibility: WM161

Due Date:

Priority: P2 - 5 DAYS

Reference #:

Project: -

Service Request:

Budget #: 170212 - WASTEWATER COLLECTION DI

Group Project:

Started: 07/24/2018

Cancel WO: N

Closed: 07/24/2018

Result: -

Closed By: ANTWON L FALLIN

Condition: -

Hours: 2.50

Usage: 0.00

Actual Qty: 17.00 LF

Address: 1071 PIEDMONT AVE NE

City: ATLANTA, GA 30309

Work Order Comments:

Work Order Logs:

Log Type:

Log By: W100

Log From Date: 07/24/2018

Log To Date: 07/24/2018

Entered MH# 23370108201 televised only 17Ft upstream against the flow Survey was abandon due to large debirs stopping the camera from walking. However crew dye test cavein for 1 hour and no dye showed or water volume picked up. The cavein never filled up which means the watre is going somewhere. This location needs more investigation.

Work Order Tasks: